


CNC EDM



Repair CNC EDM JOEMARS Brand.....

This is the machine started to on duty since 2007.

The problem was happened because of the electrical shut down during sparking. The Z Axis Servo drive unit and LVD-25A were damaged.

Service Engineer : Udomsak Sodsai

Manufacture : JOEMARS MACHINERY & ELECTRIC INDUSTRY CO.,LTD.

JOEMARS EDM, WIRE CUT & SUPER DRILL EDM

Thailand Agent : Siam Elmatech Co., Ltd.

